Attorney Docket No. 1293.131

## HE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Jin-Gyo SEO

Application No.: 10/084,342

ATTENTION

Confirmation No.: 5599

CERTIFICATE OF CORRECTION

Filed: February 28, 2002

BRANCH

Certificate

U.S. Patent No.: 6,898,223 62

Batch No.:

FEB 1 3 2006

Issued: May 24, 2005

of Correction

For:

APPARATUS FOR AND METHOD OF CONTROLLING OUTPUT OF A LASER DIODE

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 USC § 254 and 37 CFR § 1.322, to correct the error(s) shown on the attached Form PTO-1050. A check in the amount of \$100 to cover the cost of the Certificate is attached.

One or more of the errors shown on the attached Form PTO-1050 is or are within the responsibility of the undersigned; each thereof is of a clerical or typographical nature or of minor character and occurred in good faith, and the correction thereof is consistent with the prosecution record.

Respectfully submitted,

STAAS & HALSEY LLP

∕gistration No. 34

02/09/2006 JADDO1

00000087 6898223

100.00 OP

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

FEB 14 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,898,223  $\beta \mathcal{V}$ 

DATED: May 24, 2005

INVENTOR(S): Jin-Gyo SEO

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

- \* Column 11, line 49, change "converter]." to --converter.--
- \* Column 12, line 33, change "subtractor" to --subtracter--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY 1201 New York Avenue, N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,898,223

No. of add'l copies @ 304 per page Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,898,223 62

DATED: May 24, 2005

INVENTOR(S): Jin-Gyo SEO

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

- \* Column 11, line 49, change "converter]." to --converter.--
- \* Column 12, line 33, change "subtractor" to --subtracter--.

MAILING ADDRESS OF SENDER: STAAS & HALSEY
1201 New York Avenue, N.W. Suite 700
Washington, DC 20005

PATENT NO. 6,898,223

No. of add'l copies @ 304 per page